



# ANALYTIC BALANCE **BAE**

## User Manual



v.201811



**HiWEIGH**  
Weighing system & solution

An ISO9001 registered company  
@No.335 Haishen, Xingxin Road, Huinan Town, Pudong District, Shanghai 201301, China  
[www.hiweigh.com](http://www.hiweigh.com) All rights reserved, specifications subject to change without notice

Value Each Gram

# CONTENTS

<b>1</b>	<b>INTRODUCTION</b>	<b>4</b>
	OPEN BOX AND PACKING LIST	4
	IDENTIFICATION OF ELECTRONIC BALANCE UNITS	5
	USING ENVIRONMENT	6
	ADJUST LEVEL	6
	GLASS DOOR UNLOCK	6
	INSTALL WEIGHING PAN	7
	POWER SUPPLY CONNECTION	7
<b>2</b>	<b>OPERATION INTRODUCTION</b>	<b>8</b>
	FUNCTION APPLICATION MENU	8
	OPERATION OF BALANCE	8
	OPERATION CONCEPT	9
	MENU INTERFACE	9
	SELECT APPLICATION PROGRAM	10
<b>3</b>	<b>WEIGHING</b>	<b>12</b>
	APPLICATION LIST OF MENU	12
	WEIGHING	13
	WEIGHING UNIT CONVERSION	14
	PIECE COUNT	15
	WEIGHING IN PERCENT	17
	DENSITY (ONLY FOR AE J SERIES DENSITY BALANCE)	19
	INSTALL DENSITY PARTS	21
	DENSITY PARAMETER TABLE	22
	CONVERSION	25
	CALIBRATION	26
	EXTERNAL CALIBRATION	27
	INTERNAL CALIBRATION ( ONLY FOR AE C INTERNAL BALANCE )	28
<b>4</b>	<b>SETUP</b>	<b>29</b>
	SET APPLICATION LIST OF MENU	30
	CHANGE SETTING	30
	WEIGHING SETUP	31
	PRINTING SETUP	33
	SYSTEM SETUP	34
	SCREEN BRIGHTNESS	34
	SYSTEM UPDATE	34
	LINEAR CORRECTION	34
	INTERNAL CALIBRATION STANDARDIZATION	34
	RESTORE FACTORY SETIP	34
	INFORMATION OF BALANCE	35
<b>5</b>	<b>SPECIFICATION</b>	<b>36</b>

<b>PRODUCT OVERVIEW .....</b>	<b>36</b>
<b>TECHNICAL PARAMETERS .....</b>	<b>37</b>
<b>SHAPE DIMENSION FIGURE.....</b>	<b>38</b>
<b>6 TROUBLESHOOTING.....</b>	<b>39</b>
<b>FAULT INFORMATION AND SOLUTIONS .....</b>	<b>39</b>
<b>A DATA COMMUNICATION</b>	
<b>DATA COMMUNICATION.....</b>	<b>39</b>
<b>B MAINTAIN AND CLEAN</b>	
<b>MAINTAIN AND CLEAN.....</b>	<b>41</b>

# 1. Introduction

Before any assembly work, all scales from the main power supply must be disconnected

## Open box and Packing List

Open the packing must be careful to remove all the accessories.

After opening the equipment, please check it immediately if there are any external damage.

If you detect any damage, please contact with after-sales service center.

Safe keeping any parts of packing and packaging in order to transport to use in the future. During the period of shipment, please pull out the cable!

The attached device consists of the following parts


AE Series Balance

- Weighing Pan
- Calibration Weight (expect AE C)
- Unlocked Pen for Glass Doors
- Manual
- AC Power Adapter
- Windbreak
- Quality Guarantee

\*Density Parts ( Only for AE J)

- C-Style Bracket
- Arched Glass
- Standard weight
- Shelve Table
- Testing Shelf X2
- Retainer Ring


## Identification of Electronic Balance Units



NO	Name	NO	Name
1	Touch Screen	10	Testing Shelf*
2	Unlocked Pen for Glass Doors	11	C-Style Bracket*
3	Panel shelter	12	Arched Glass*
4	Windbreak	13	Shelve Table*
5	Weighting Pan	14	Retainer Ring*
6	Level Indicator	15	RS232 Port
7	Leveling Foot	16	Power Adapter Socket
8	Windproof Cover	17	USB port (*optional)
9	Glass Door Lock	18	Under Hook

\*Density Parts (only for AE J Series)

## Using Environment




For high resolution analytical and precise balance, the right placed place is the key for accurately weighing. So please ensure that:

- Stable and no vibration position, as far as possible be level
- Avoid direct sunlight
- Avoid strenuous temperature variations
- Avoid air convection

Best placed place: the corner of shelter, stable table, as far as possible from the door, window, radiator and the outlet of air condition.

## Adjust Level



Through regulating the leveling foot, make the level bubble moving to the center of circle (as shown).


Notice: Please adjust level, when the balance moves to a new place.

## Glass door unlock



This series balance owns function to lock the glass door. Use unlock pen to click yellow part then the glass door could open.

## Install Weighing Pan



As show:

1. Install windbreak
2. Install weighing pan

## Power connection



Using the wrong power adapter may cause severe shock, and damage to equipment.  
Use the correct power adapter for the main power supply.

Please use only the original ac power adapter.

Please make sure the rated voltage marked on the ID tags with local power supply voltage is consistent.

Must be according to your country/region applicable specifications for the power supply connection.

- 1) Insert the ac power adapter into the socket on the reverse of the balance.
- 2) Connect the ac power adapter socket (mains)



Preheat time:

In the use of this series balance, in order to obtain accurate weighing results, please preheat balance more than 60minutes for first using.

If the balance in environment that has different temperature, should be appropriately increased preheat time.



## 2. Operation Introduction

### Function Application Menu

Function Application Menu is composed by three functions key and one standby key.



Application (to select weighing program)



Setup (set basic setup and change)



Calibration (to calibrate balance when move place or have error of weighing result)



Standby (switch balance standby)

### Operation of Balance



Start/OFF (Standby) Balance

After connecting the power supply, the balance into the startup interface.

Balance self-inspection.




Balance into weighing mood

+ 0.0000 g



If the balance must be switched to standby mode, please select the menu key.



Into Application interface



Should be selected standby in application interface

Switch balance into standby

Balance in the system to enter standby mode.

standby...



Standby mode, touch any part of screen to exit the standby mode.

## Operation Concept

The basic interface and operation of balance

Operating on a screen and display elements



Sharp tools (such as ballpoint pen) might damage the equipments. Could wear laboratory gloves to operate.



1	Toolbar the currently available button Including: Zero Tare Print
2	Max weighing range d actual degree value
3	Current weighing value
4	Weighing unit (click unit to switch unit)
5	Show current application.
6	Menu key: to switch application menu
7	Error warning, click to see the error information.

## Menu Interface

Select application program through application menu



Click this bottom into the application interface at any program.



1	Select area, to select application program. Including: weighing, counting, percentage, density, conversion, check weight and peak hold.
2	Standby: switch balance to standby mood
3	Function select area: application、 setup、 calibration

## Select Application Program



Select application program you need. (such as weighing)



Select weighing program, show as picture.

## 3 Weighing

### Application List of Menu



#### Weighing

The weighing is as default application in the first start. This application is used to determine the sample weight within range.



#### Counting

Used to determine quantity of almost same weight sample. Can calculate already counting the weight of the reference sample, and then weighing on the unknown number of objects. Balance will show the number of objects, and the weight of single piece.



#### Percentage

Used to determine the percentage of sample.



#### Density

Used to test density of solid or liquid sample



#### Conversion

Used to plus the certain number.

## Weighing

Objective: to determine the weight of sample within the weighing range



Menu key



Select weighing



Weighing interface

+ 0.0000 g




Zero empty weighing pan/ select 0 to zero balance.



Tare

If you use a container to weight, put the container on the weighing pan, then choose tare to remove the tare weight. Then balance will show zero again.



Put sample on the weighing pan

When the value does not change and the unit shows black, then could read value.


## Weighing Unit Conversion

Objective: Configure weighing unit



Click unit to switch other weighing unit

+ 0.0000 g



Show Units interface

Choose the unit you need.

### Weighing unit conversion factor

Unit	Factor	Shown
Gram	1.0000000000	g
Carat	5.0000000000	ct
Ounce	0.03527396200	oz
Newton	0.00980665000	N
Pound	0.00220462260	lb
Gold ounce	0.03215074700	ozt

## Counting

Objective: to determine the number of weight almost equal parts. It can calculate the weight of the reference sample, then to weigh the unknown number of objects. Balance will show the number of objects, and the weight of single piece.

Minimize counting error:

- ensure that the average distribution of the weight of each part.
- the more reference number, the higher the accuracy.



Menu key




Select counting

Shown counting interface




default reference number: 10 pc

+ 0.0000 g




If want to change number, please select gray bottom.



Choose the number needed



Zero balance




Put container on the weighing pan



Tare balance





Put the sample on the container

Shown the weight of sample



+ 3.8818 g



Press start



Shown reference number

and shown the weight of each sample

10 PCS




Put the unknown-number objective on the container

The balance will calculate the number and shown it.



31 PCS




Press End to back to the menu

## Weighing in Percent

Objective: to determine the percentage of the sample and the reference weight related or percentage difference.



Menu Key



Select Percentage




The default percentage is 100%

+ 0.0000 g



Press gray bottom to change percentage.



Choose you needed



Zero balance



Put container on the weighing pan



Tare balance



Put the reference sample on the container



Shown reference percentage

100.000 %

Shown the weight of reference sample



Put the sample on the container



Balance will show the percentage of sample

226.178 %



Press End to back to Menu

## Density (Only for AE J Series Density Balance)

Objective: to determine the density of solid and liquid



Menu Key




Select density mood

Shown density interface


Shown default standard material water



If change standard material, please press gray bottom.



Select the standard material you needed



Put the testing shelf on the density part

Ensure that the test frame hanging basket fully immersed in the standard liquid, to support the sample later.



If the distilled water is used as the standard liquid, please add 3 drops of surfactant to reduce surface tension plays the role of the measurement result.

Zero balance


▶0◀ ▶T◀ 

Max: 220g d=0.0001g

+ 0.0000 g

  Standard Material *g/cm<sup>3</sup>*  
Water (20°C) 0.99823 **START**

**START** Press start





Put the sample on the densely part


Shown the sample weight on the air

▶0◀ ▶T◀ 

Max: 220g d=0.0001g

+ 11.8949 g

  Standard Material *g/cm<sup>3</sup>*  
Water (20°C) 0.99823 **START**



Take off the sample and put it on the basket

Shown the weight of sample on the liquid. Press next

▶0◀ ▶T◀ 

Max: 220g d=0.0001g

+ 8.0159 g

 BUOYANCY Mass  
+ 11.8949 g **NEXT**

Balance will calculate the density of sample



1.4813  $g/cm^3$




Press End to back to menu




1) Adjust balance level


2) Install the retainer ring



3) C bracket is installed on the scale; can be flexible with your hand lightly in the activity.



4) Put table on the table panel. Put aside a round card on the edge of the retainer ring. Rotary level do not touch C shelf.



5) Put arched glass

**Density Parameter Table**

	Valid decimal:3 (Repetitive $\leq \pm 0.0001\text{g/cm}^3$ )		Valid decimal:4 (Repetitive $\leq \pm 0.0001\text{g/cm}^3$ )	
Density ( $\text{g/cm}^3$ )	Sample Quality ( $\geq \text{g}$ )	Sample Quality ( $\geq \text{g}$ )	Sample Quality ( $\geq \text{g}$ )	Sample Quality ( $\geq \text{g}$ )
0.10	0.020	0.020	0.0020	0.0020
0.20	0.080	0.080	0.0080	0.0080
0.30	0.180	0.180	0.0180	0.0180
0.40	0.320	0.320	0.0320	0.0320
0.50	0.500	0.500	0.0500	0.0500
0.60	0.720	0.720	0.0720	0.0720
0.70	0.980	0.980	0.0980	0.0980
0.80	1.280	1.280	0.1280	0.1280
0.90	0.620	1.620	0.1620	0.1620
1.00	2.000	2.000	0.2000	0.2000
2.00	8.000	8.000	0.8000	0.8000
3.00	18.000	18.000	1.8000	1.8000
4.00	32.000	32.000	3.2000	3.2000
5.00	50.000	50.000	5.0000	5.0000
6.00	72.000	72.000	7.2000	7.2000
7.00	98.000	98.000	9.8000	9.8000
8.00	128.000	128.000	12.8000	12.8000
9.00	162.000	162.000	16.2000	16.2000
10.00	200.000	200.000	20.0000	20.0000
11.00	242.000	242.000	24.2000	24.2000
12.00	288.000	288.000	28.8000	28.8000
13.00	-	338.000	33.8000	33.8000
14.00	-	392.000	39.2000	39.2000
15.00	-	450.000	45.0000	45.0000

**Commonly used material density table.**

No	Name	Density	No	Name	Density
1	Construction Steel	7.85	27	Interleaving Paper	0.9
2	Cast Steel	7.8	28	Fiber Paperboard	1.1~1.4
3	Grey Cast Steel	6.8~7.2	29	Waterproof Paper	1.0~1.1
4	High-Quality Cast Iron	7.0~7.6	30	Felt	0.24~0.38
5	Malleable Cast Iron	7.2~7.4	31	Rubber	1.3~1.8
6	Hard Alloy (Tungsten Alloy)	13.9~14.9	32	Cork	0.25~0.45
7	Tungsten Carbide (Titanium Alloy)	9.5~12.2	33	Mica	2.8~3.2
8	Aluminum	2.77	34	Amino Plastic	1.45~1.55
9	Pressure Processing Aluminum Alloy	2.67~2.8	35	Asbestos Cloth Plastic	2
10	Foundry Aluminum Alloy	2.6~2.85	36	Asbestos Screen Plastic	2
11	Babbitt Metal	7.5~10.5	37	Fibre Resin	1.35~1.45
12	Red Copper	8.89	38	Paper Fillin Plastic	1.4~1.7
13	Pressure Processing with Brass	8.4~8.85	39	Fabric Bakelite	1.3~1.4
14	Casting Brass	8.622	40	Polyvinyl Chloride Plastics	1.28~1.37
15	Cast Bronze without Tin	7.5~8.6	41	Celluloid	1.35~1.40
16	Pressure Processing Tin Bronze	8.65~8.9	42	Organic Glass	1.18
17	Nickel	8.9	43	Glass	2.5~2.7
18	Manganese	7.44	44	Leather	0.86~1.02
19	Magnesium	1.74	45	Graphite	1.9~2.3
20	Tin	7.3	46	Gasoline	0.66~0.75
21	Lead	11.34	47	Kerosene	0.78~0.82
22	Silver	10.5	48	Alcohol	0.807~0.810
23	Gold	19.361	49	Charcoal	0.27~0.58
24	Platinum	21.561	50	Smokey Coal	1.2~1.5
25	Zinc (Casting)	6.872	51	Anthracite	1.4~1.8
26	Wood (Humidity 15%)	0.4~1.05	52	Coke	0.27



## Conversion

Purpose: used to weight value plus number





Menu Key



Select conversion mood

Conversion interface



Press gray bottom to change conversion



Use number key to enter conversion

Then press OK to enter

Press cancel to back to menu



Zero balance



Select Start



Put sample on the weighing pan



Max: 220g

d=0.0001g

The number is shown that weight plus conversion

95.1490 o



Press end to back to menu



## Calibration



Before using balance, must calibrate in the place of placing balance.  
Calibration can choose external or internal calibration.

Time and frequency

To achieve the highest accuracy, please regular calibrate balance

Every day calibrate balance after start.

Every time, after balance level adjustment.

Environmental conditions (temperature, temperature or pressure) changes.

Location changes or move to a new place.

Balance with the following options:

External calibration,

Internal calibration (only for AE C series )

## External Calibration





Clean weighing pan




Select calibration


Select External Calibration.



Place the calibrated weight on the pan center.




The balance starts calibrating until complete of it.




According the tips, remove the weights, and then balance start calibrating. When finish calibration, press enter.

### Internal Calibration (Only for AE C internal balance)

Clean weighing pan





Select calibration



Select Internal Calibration.

The balance will do the internal calibration, when finish, please press enter.



## 4 Setup

### Set Application List of Menu



Weighing set<sup>↵</sup>  
Set basic weighing function<sup>↵</sup>



Printing set<sup>↵</sup>  
Set printing mood<sup>↵</sup>



System set<sup>↵</sup>  
Set system parameter and restore factory set<sup>↵</sup>



Information<sup>↵</sup>  
Balance basic information<sup>↵</sup>

## Enter menu and change set



Click the set you needed

## Select item to change



This is the current selected.

Change the settings the settings is instant activation, do not need to restart.

## Weighing Setup

← WEIGHING

Environment

Stability

Display

Tare

Auto. Zero

Zero on Boot

**Environment**

Environment  
Environmental factors will interfere with balance performance. If there is vibration or air movement in the weighing environment, choose UNSTABLE.

STABLE UNSTABLE

Default: STABLE

### Weighing Environment

Environment factors have inevitable interference and influence on the balance process. If air or vibration in the experimental environment is large, please choose unstable.

← WEIGHING

Environment

Stability

Display

Tare

Auto. Zero

Zero on Boot

**Stability**

Stability  
When weighing results are stable within a certain range, the balance will immediately show stability. Before achieving stability, the weighing unit (example: g) will be displayed in grey color. The weighing unit will change to black when the weighing is stable.

SLOW High Accuracy MEDIUM Med. Accuracy FAST Low Accuracy

Default: SLOW

### Stability

When weighing results are stable within a certain range, balance will immediately show stability. Before achieving stability, weighing units show grey. When the balance is stable, the units will become black.

← WEIGHING

Environment

Stability

Display

Tare

Auto. Zero

Zero on Boot

**Display**

Display  
Users can choose a display mode according to their weighing process requirements.

SHOW ALL DIGITS ALWAYS HIDE THE LAST DIGIT ALWAYS  
SHOW THE LAST DIGIT AFTER STABILITY SHOW ALL DIGITS AFTER STABILITY

Default: SHOW ALL DIGITS ALWAYS

### Weighing Display

Customer could select all kinds of display according to needed.

← WEIGHING

Environment

Stability

Display

Tare

Auto. Zero

Zero on Boot

**Tare**

Tare  
Enable this option to allow the balance to be tared only when stable. If disabled, the balance can be tared whether stable or not.

ENABLE DISABLE

Default: ENABLE

### Tare

Use this function means that when the balance is stable, then do tare function.

← WEIGHING

Environment

Stability

Display

Tare

Auto. Zero

Zero on Boot

**Auto. Zero**

Auto. Zero  
Enable this option to prevent the weight reading from drifting near the zero position.

ENABLE DISABLE

Default: ENABLE

### Auto Zero

Use this function, the balance will automatically do zero near zero position.



← WEIGHTING

- Environment
- Stability
- Display
- Tare
- Auto. Zero
- Zero on Boot**

**Zero on Boot**  
Upon startup, the display will reset to zero.

ENABLE

DISABLE

Default: ENABLE

### Zero on boot

When startup, balance will automatically boot to zero.

## Printing Setup

### Set print mood

← PRINTING

Mode

Baudrate

Data Bits

Stop Bits

Parity

Mode

Set balance printing mode.

MANUALLY SEND INSTANTANEOUS VALUE	MANUALLY SEND STABLE VALUE
AUTOMATICALLY SEND INSTANTANEOUS VALUE	AUTOMATICALLY SEND STABLE VALUE

Default: MANUALLY SEND STABLE VALUE

Print mood (set balance print mood)

← PRINTING

Mode

Baudrate

Data Bits

Stop Bits

Parity

Baudrate

Set baud rate of serial port. (bps)

1200	2400	4800
9600	19200	38400
57600	115200	

Default: 9600 bps

Baud rate (set baud rate of balance printing)

← PRINTING

Mode

Baudrate

Data Bits

Stop Bits

Parity

Data Bits

Set data bits of serial port.

5 bits	6 bits
7 bits	8 bits

Default: 8 bits

Date bits (set data bits of balance)

← PRINTING

Mode

Baudrate

Data Bits

Stop Bits

Parity

Stop Bits

Set stop bits of serial port.

1 bit	2 bits
-------	--------

Default: 1 bit

Stop bits (set stop bits of balance)

← PRINTING

Mode

Baudrate

Data Bits

Stop Bits

Parity

Parity

Set parity of serial port.

NONE	ODD
MARK	EVEN
	SPACE

Default: NONE

Parity (set parity of balance)

## System set

← SYSTEM

LCD Brightness

System Update

Linear Correction

Int. CAL. Std.

Restore

LCD Brightness  
Set screen brightness of balance display.

Low MEDIUM HIGH

Default: HIGH

### LCD Brightness

Set screen brightness of balance display

← SYSTEM

LCD Brightness

System Update

Linear Correction

Int. CAL. Std.

Restore

System Update  
Update balance system kernel. Balance will restart automatically after the completion of the system update.

START

### System update

← SYSTEM

LCD Brightness

System Update

Linear Correction

Int. CAL. Std.

Restore

Linear Correction  
This balance has been factory calibrated for linearity, correction is not typically required. However, linearity can be corrected by performing this operation. A range of standard weights are required for linear correction.

START

### Liner correction

← SYSTEM

LCD Brightness

System Update

Linear Correction

Int. CAL. Std.

Restore

Internal Calibration Standardization  
Perform this operation if the internal calibration is not accurate.

START

### Inter calibration standardization

← SYSTEM

LCD Brightness

System Update

Linear Correction

Int. CAL. Std.

Restore

Restore  
Restore all the settings to factory default. Balance will reboot automatically after completion.

RESTORE

### Restore factory set

## Information

← ABOUT

Manufacturer  
HWEIGH TECHNOLOGIES LIMITED

Model:  
Kernel Version: 0.842  
Interface Version: 0.94.1

## Manufactory information



info@hiweigh.com | www.hiweigh.com

## 5. Specification

### Product Overview

Balance standard configuration

Balance power output: 100-240VAC; 50, 60Hz

Output: DC12V; 600mA

### Raw material

Base: die casting aluminum alloy; paint

Cover: plastic (ABS/PC)

Weighing pan: stainless steel

### Protection level

Dustproof and waterproof

Level of pollution prevention: II

Level of installation: II

### Use of environment requirements

Balance of technology parameters in following conditions:

Working environment temperature: ①  $20^{\circ}\text{C} \pm 2.5^{\circ}\text{C}$ , the temperature fluctuation is not more than  $1^{\circ}\text{C}/\text{h}$

②  $20^{\circ}\text{C} \pm 7.5^{\circ}\text{C}$ , the temperature fluctuation is not more than  $5^{\circ}\text{C}/\text{h}$

Relative humidity: ① 50% ~ 75%;

② 40% ~ 80%

Working voltage ① 12VDC

② 12VDC

In a stable environment, the preheating time of at least 60 minutes of the scale, the power supply shall be reliable grounding.

### Technical Parameters

### External Calibration Models

Model	BAE124	BAE224	BAE223	BAE323	BAE523
Actual division value (d)	0.0001	0.0001	0.001	0.001	0.001
Weighing Capacity (Max) (g)	120	220	220	320	520
Repeatability (s)	0.0001	0.0001	0.0001	0.0001	0.0001
Calibraion Weight	100	200	200	200	500
Type	Standard				
Dimension (W/D/H) (mm)	365×225×338				
Packing Measurement (W/D/H) (mm)	500×310×450				
Pan Size (mm)	φ 90				
Effective height above pan (mm)	160×165×200				
Net Weight (kg)	5.5				
Gross Weight (kg)	8				


### Internal Calibration Models

Model	BAE124C	BAE224C	BAE223C	BAE323C	BAE523C
Actual division value (d)	0.0001	0.0001	0.001	0.001	0.001
Weighing Capacity (Max) (g)	120	220	220	320	520
Repeatability (s)	0.0001	0.0001	0.0001	0.0001	0.0001
Calibraion Weight	100	200	200	200	500
Type	Internail Calibration				
Dimension (W/D/H) (mm)	365×225×338				
Packing Measurement (W/D/H) (mm)	500×310×450				
Pan Size (mm)	φ 90				
Effective height above pan (mm)	160×165×200				
Net Weight (kg)	5.5				
Gross Weight (kg)	8				

### Density Weighing Models

Model	BAE124J	BAE224J	BAE323J	BAE523J
Actual division value (d)	0.0001	0.0001	0.001	0.001
Weighing Capacity (Max) (g)	120	220	320	520
Repeatability (s)	0.0001	0.0001	0.0001	0.0001
Calibraion Weight	100	200	200	500
Type	Density			
Dimension (W/D/H) (mm)	365×225×338			
Packing Measurement (W/D/H) (mm)	500×310×450			
Pan Size (mm)	φ 90			
Effective height above pan (mm)	160×165×200			
Net Weight (kg)	6			
Gross Weight (kg)	8			

Figure Dimension



# 6 TROUBLESHOOTING

## Fault Information and Solutions

The balance will show the fault, and tip you to do how to solve it.

### A Data communication

This series of balance is equipped with standard RS232 serial port output, can be connected to the computer and printer. With the microcomputer serial port connections are as follows:

Microcomputer (9 core hole) ----- Balance (9 core hole)

2 (RXD) ----- 2(TXD)

3 (TXD) ----- 2(RXD)

5 (GND) ----- 5 (GND)

Balance a serial port baud rate 9600 BPS.

Data format for 10, one of the start bit (0), 8 bits of data (ASCII, low in the front), a stop bit (1).

No odd-even check

For continuous output data, don't need special reading command.

0	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15
symbol	blank	weighing value									blank	unit	CR	LF	
±	␣	␣	1	9	9	.	9	9	9	9		g	CR	LF	

0: Expressed as a plus or minus sign


2-10: According to quantity, for the right alignment, less than a complement by Spaces; Consistent with the balance display;

12-13: Unit may show is different with balance display

Balance display	Output	
	13	14
g	g	blank
oz	o	z
ozt	g	z
ct	c	f
lb	l	b
N	n	blank



## Port



## **B Maintain and clean**

Power off: disconnect device connected to the power supply.

If necessary, disconnect the data cable connected to balance

Ensure that no liquid, or dust into the balance or ac adapter.


Do not open the balance or the ac power adapter.

Do not use the volume or composition of abrasive cleaner, which ultimately may cause damage to equipment.

Please use soft non-fluffy cloth to clean the enclosure or weighing pan, if necessary please use neutral detergent.

After cleaning, use dry soft cloth to wipe balance.





v.201811  
User Manual  
**BAE**