



WEIGHT INDICATOR X704 User Manual

v.201811





Safety precautions



WARNING!

- ▲ Do not use X* Series indicators in hazardous area or in dusty environments.
- ▲ Never flood the Indicator, immerse it in liquid or pour liquids on it.
- ▲ Do not expose indicator to either direct sun light or any heat sources.
- ▲ Do not open the indicator! The warranty is void if this stipulation is ignored. The indicator may only be opened by authorized persons.



DANGER!

Electric shock hazard!

▲ Always unplug AC adapter before performing any work on the indicator

Hazard of electric shock if the power cable is damaged!

▲ Check the power cable for damage regularly. Unplug the power cord immediately if the power cable is damaged.



Disposal

In conformance with the European Directive 2002/96/EC on Waste Electrical and Electronic Equipment (WEEE), this device may not be disposed of in domestic waste. This also applies to countries outside the EU as per their specific regulations.

Please dispose of this product in accordance with local regulations at the collecting point specified for electrical and electronic equipment.

If you have any questions, please contact the responsible authority or the distributor from which you purchased this indicator.

Should this indicator be passed on to other parties (for private or professional use), the content of this regulation must also be related.

The indicator has a rechargeable internal battery. The battery contains heavy metals. Please observe the local regulations on the disposal of environmentally hazardous materials.

INDEX

Power source Power consumption Components included Connection of indicator X704 to a loadcell Requirements for an optimum installation Installation Keyboard description Piece-counting function Tare function Weights accumulation Functions setting Advanced functions setting		
Power consumption Components included Connection of indicator X704 to a loadcell Requirements for an optimum installation Installation Keyboard description Piece-counting function Tare function Weights accumulation Functions setting Advanced functions setting Setting parameters A 4 4 4 4 4 4 4 4 4 4 4 4 5 5	Specifications	4
Components included4Connection of indicator X704 to a loadcell5Requirements for an optimum installation5Installation6Keyboard description6Piece-counting function7Tare function7Weights accumulation7Functions setting8Advanced functions setting9Setting parameters10	Power source	4
Connection of indicator X704 to a loadcell Requirements for an optimum installation Installation Keyboard description Fiece-counting function Tare function Weights accumulation Functions setting Advanced functions setting Setting parameters 5 5 6 7 7 8 8 9 9 9 9 9 9 9 9 9 9 9	Power consumption	4
Requirements for an optimum installation Installation Keyboard description Piece-counting function Tare function Weights accumulation Functions setting Advanced functions setting Setting parameters Setting parameters	Components included	4
Installation6Keyboard description6Piece-counting function7Tare function7Weights accumulation7Functions setting8Advanced functions setting9Setting parameters10	Connection of indicator X704 to a loadcell	5
Keyboard description6Piece-counting function7Tare function7Weights accumulation7Functions setting8Advanced functions setting9Setting parameters10	Requirements for an optimum installation	5
Piece-counting function Tare function Weights accumulation Functions setting Advanced functions setting Setting parameters 7 7 7 7 7 7 7 7 8 8 10	Installation	6
Tare function 7 Weights accumulation 7 Functions setting 8 Advanced functions setting 9 Setting parameters 10	Keyboard description	6
Weights accumulation7Functions setting8Advanced functions setting9Setting parameters10	Piece-counting function	7
Functions setting 8 Advanced functions setting 9 Setting parameters 10	Tare function	7
Advanced functions setting 9 Setting parameters 10	Weights accumulation	7
Setting parameters 10	Functions setting	8
	Advanced functions setting	9
Guarantee 11	Setting parameters	10
	Guarantee	11

SPECIFICATIONS

Model	X704
Accuracy	III
Sensitivity	1.5~3.0mV/V
Linear	≤0.01%F.S
Voltage	DC: 5V
Division	1/2/5 option
Speed	20 times per second
Internal resolution	300,00/600,00

POWER SOURCE

Input: AC 120~240V Output DC 10V/600mA

POWER CONSUMPTION

Main system: Approx. 24.1mA
 Main system (RS-232): Approx. 44mA
 Standby: Approx. 19.2mA
 Battery duration: Approx. 120


COMPONENTS INCLUDED

- 1. This user manual (please read it carefully before to use the indicador).
- 2. The indicator Series X704
- 3. The AC/Adaptor.

!Keep the original package. It could be useful in the future to transport the indicator.

CONNECTION OF INDICATOR TO A LOADCELL

Connector of 5 pins connector.



INDICATOR	LOAD CELL
+E (1)	+Excitation
-E (2)	Excitation
+S (3)	+Signal
-S (4)	Signal
GND (5)	(GND) shield

If working with 7-wire load cells, short connect SENSE+ with +E (pin1), SENSE- with -E(pin2).

REQUIREMENTS FOR AN OPTIMUM INSTALLATION


To obtain maximum performance and best results, we recommend to install the scale or indicator according to the following requirements:

- a) Don't expose the indicator to direct sunlight.
- b) Don't submit it to atmospheres with corrosive gases.
- c) Keep it in an environment free of dust and dirt.
- c) Work at temperatures between 0° and 40° C.
- e) Use the indicators in environments with humidity lower than 95% HR.
- f) Keep it away from those equipments which produce magnetic interferences and acoustical noise.

INSTALLATION

- 1. Place the platform on a firm and stable surface.
- 2. Before to connect the indicator, make sure that platform is empty.

KEYBOARD DESCRIPTION





Function 1. Press this key for 2 seconds to turn off the indicator.

Function 2. Press this key to confirm data in setting parameters mode.



Function 1. Press this key to turn on the indicator.

Function 2. To reset the weight to 0. The displayed weight value has to be less than +/-2% of maximum capacity.

Function 3. To subtract the weight of a container and then obtain the net weight of product (Tare function). The container's weight must be higher than 2% of maximum capacity.



Function 1. To enter to piece-counting function.

Function 2. To change the parameters in setting parameter mode.



Function 1. To accumulate weights.

Function 2. To print data.

PIECE-COUNTING FUNCTION

- 1. Press the wis key for 2 seconds, the display will show "0" "kg"
- 2. Press again the key, the display will show "C 10"
- 3. To select the sample value, press the key
- 4. Put on the platform the selected number of pieces.
- 5. Press the off to confirm.
- 6. Display will show the number of pieces placed on platform.
- 7. Add the rest of pieces to be counted, the display will show the total number of pieces.
- 8. Press the will return to normal weighing mode.

Note: The sample unit weight must be higher than 0,2d.

TARE FUNCTION

- 1. Place a container on the platform.
- 2. Press the (N) key.
- 3. The balance will subtract the weight of container, display will show 0
- 4. Put the product to be weighed in the container.
- 5. Display will show the product's weight (net weight)

Note: The container's weight must be higher than 2% of maximum capacity.

WEIGHTS ACCUMULATION

- 1. Place the product on the platform.
- 2. Press the Mt key to save in memory his weight.
- 3. Display will show the weighing number and weight's product.
- 4. Remove the product from platform, display will show "0"
- 5. Place a new product on the platform.
- 6. Press again the key to accumulate the weighing.
- 7. Repeat this operation as many times as it is necessary.
- 8. Once finished the accumulation, press the (M) key, to read the total weight.
- 9. Display will show: weighing times and total weight accumulated.
- 10. To clear, press the key for 2 seconds.

FUNCTIONS SETTING

- 1. To access to Functions setting, press the key, display will show the message "UF __1".
- 2. Press the key to select the desired parameter, from "UF-1" to "UF---9"

Parameter	Function	Operation
UF-1	Check internal value and battery voltage	Press off, display will show the internal value, pressing again this key, display will show the battery voltage. Press off to exit.
UF-2	Parameter not available	
UF-3	Auto power off setting	Press off, display will show AOFF 00. Press to change the parameter Press to select the desired mode: AOFF00 - Auto-power off disable. AOFF01 - The indicator will auto power off in 1 minute if not use it Press off to exit.
		Press to exit.
UF-4	Standby setting	Press to change the parameter. Press to select the desired mode. Press off to exit.
UF-5	Parameter not available	
UF-6	Output RS-232	Optional
UF-7	Speed adjustment	Press off key
		Press to select: 1. Fast speed 2. Normal speed 3. Slow speed Press of to exit.
UF-8	Division range display	Press off key.

		Press to select the desired value. Press to exit.
UF-9	Gravity value	Press the off key, display will show the G value of factory. If you want to change it according to new place (Country), press off and to select the desired value. Press off to exit.

ADVANCED FUNCTIONS SETTING

- 1. To access to advanced functions setting, press the the key and without release it press the key, display will show "ECF __1".
- 2. Press to select the desired parameter, from "ECF-1" to "ECF---3"

Parameter	Function	Operation
ECF-1	Check maximal load (span)	Press off, display will show CALZ, empty the platform and press again the off key to put display reading to zero Press to enter the value.
		Put a weight on the platform and press off key to confirm and exit.
ECF-2	Zero calibration	Press OFF key, display will show CALZ, empty the platform and press again the OFF key to put display reading to zero and exit.
		Press OFF key Press OFF key.
ECF-3	Span calibration	Press to enter the value of calibration weight

	Put the calibration weight on the platform and press off to confirm and exit.
--	---

SETTING PARAMETERS

- 1. To access to setting parameters, with indicator turned off, press and hold the without release it, press the key continuously during the initial countdown.
- 2. When countdown is finished, the display will show P0000, press the digit flashes P0000, then press two times the key, the display will show P0020.
- 3. Press the Fig. key, the display will show LF1.
- 4. Use the key to select the LF1 or LF2 modes and press to enter to desired mode.

LF1: Calibration menu

o Press the OFF key to enter to Calibration menu, the display will show CALZ (zero calibration value), press the OFF key to modify the calibration weight value. Use the Mth key to move a digit to the right and use the OFF key to increase the digit value. Once entered the value, place the calibration weight on the weighing pan and then press OFF . The value will flash continuously, press again the OFF to confirm. A series of dashed will be displayed ------ and immediately the calibration will be completed.

LF2; Parameters setup menu

- o Press the off key to enter to Parameters setup menu, the internal counts will be displayed.
- o Press the OFF to continue.
- o Display will show: 1 0 0 0 0 1 A B C D E F

This menu, should only be modified for special configurations.

If necessary to modify:

- o A: Metrical system 0: None 1: kg 2: T 3: g
- o B: American system 0: None 1: lb 2: lb oz
- o C: Other units 0: None 1: TW Kg 2: HK Kg 3: VISS
- o D: Pieces 0: Off 1: On
- o E: Dual range 0: Off 1: MULTI INTERVAL 2: MULTIRANGE
- o F: Calibration unit 1: European 2: American
- Press the OFF key to continue
 - Select the maximal capacity of the balance, taking in mind the decimals, for exemple for 150 kg -20g
 015000 (The last two zeros respecte the decimal points 150.00)
- Press the OFF key to confirm

 To select the decimal point, press the key to view the different options and the OFF to confirm.
- Press the OFF to confirm.
- To configurate the resolution of the balance, press the options and the to confirm.

GUARANTEE

This indicator is guaranteed for one year from the delivery date. The guarantee cobres any fabrication defect of the material.

During this period, HIWEIGH coves the manpower and the spare parts for the reparation of the scale.

This guarantee does not cover the failures caused by an inappropriate use or overload.

The guarantee does not cover the freight cost (transport) necessary to repair the indicator.





v.201811 User Manual X704

