









Value Each Gram



1	Main Specifications	2
2	Dimensions	3
3	Front Overlay and Keypad	4
4	Rear Back Interface	4
5	Load Cell Interface	6
6	Serial Interface	7
7	I/O	7
8	Analog Quantity Output	9
9	Parameter Set	10
	9.1 Enter Set Menu	10
	9.2 Quit Setting	10
	9.3 Main Set Menu	10
	9.4 System Parameter Set	11
	9.4.1 Scale Set	11
	9.4.2 Operation Set	15
	9.4.3 Batching Set	17
	9.4.4 Communication Set	23
	9.4.5 Analog Quantity Set	25
	9.4.6 Diagnosis and Maintenance	27
	9.5 Recipe Parameters Set	31
	9.6 Printing Table Set	35
	9.7 System Set	36
10	Appendix 1: Communication Protocol	37
	10.1 Continuous Transmitting Format A	37
	10.2 Command Transmitting Format A	37
	10.3 Continuous Transmitting Format B	37
	10.4 Command Transmitting Format B	38
	10.5 MODBUS Transmitting	39
	10.6 Multi Materials Jointed Work With Relay Connected Drawing	42

CONTENTS

1. MAIN SPECIFICATIONS

Specifications		
Housing	Metal shielded housing, with OLED display	
dimensions (w × h × d)	110mm×62mm×116mm	
Protection	IP65 (front panel)	
Operation Condition	Temperature: $-10^{\circ}C \sim 40^{\circ}C$ ($14^{\circ} \sim 104^{\circ}$ F) Relative humidity: 10% -95\%, non-condensing	
Power	+24VDC $(\pm 15\%)$, Consumption <6W	
Display	128×64 dot matrix、Yellow-Green OLED	
Display resolution	Max.100,000	
Platform	1 with analog load cell	
Load cells	1~6 x 350 Ohm (Sensitivity is 2 or 3mV/V)	
A/D Speed	200Hz (200times/s)	
Excitation Voltage	5VDC	
Min.Input sensitivity	0.6µV/d	
Keypads	4 function keys	
Basic	Serial Output: RS232 or RS485 I/O interface: 1xln 4xOut	
Optional	I/O interface: 4xIn 8xOut Analog signal $0\sim 20mA$, $4\sim 20mA$, $0\sim 24mA$ $0\sim 10V$, $0\sim 5V$, $-5\sim +5V$, $-10\sim +10V$	

2. DIMENSIONS

Housing Dimensions





Installation dimensions



Installation hole size 92×45mm

3. Front Overlay and Keypad



Display



Signs

Status	Note
7	Stable, on for dynamic mode, off for static mode
B/G	Gross weight
Net	Net weight
Kg	Unit
Stop	Stop
Run	Run
M1~M4	Material 1-4
>>	Fast filling
>	Fine filling

Keys' functions for parameter set or choose

Keys	Menu	Parameter set	Parameter Input
►04 ZERO	Return	Return	Cancel and Quit
◆ TARE	Up	Previous	Increase digits
SELECT	Down	Next	Move right
₽	Enter	Quit confirm	Quit confirm

4. Rear Back Interface



Y320 Basic



Y320-IO Type



Y320-DA Type

5. Load Cell Interface

It can be connected with $6x350\Omega$ analog load cells (around 58Ω minimum resistance), to confirm the range of the load cells, the total resistance (TSR) can be calculated with the formula as below:

TSR = $\frac{\text{Input resistance } (\Omega)}{\text{Load cell numbers}}$

Before connecting the load cells, make sure the TSR is above 58Ω , if it's less, the indicator can't work. Besides this, the cable distance must be considered, too, below is the maximum distance suggested:

TSR (Ω)	24# cable (m)	20# cable (m)	16# cable (m)
350	243	610	1219
58 (6-350 Ω)	40	122	224

Load cell interface definitions:

Pins	Signal	Note	
+EXC	+Excitation	4-wire load cells short connected	
+SEN	+Sense		
+SIG	+Signal		
SHD	Shield		
-SIG	-Signal		
-SEN	-Sense	A-wire load cells short connected	
-EXC	-Excitation		





6-wire load cell or junction box

4-wire load cell or junction box

6. Serial Interface

It has only one serial interface, to change it by switch for RS232 or RS485, method as below:

Pins	RS-232	RS-485
Bridge Joint Pin signs	Rear A ••• ••• ••• ••• ••• ••• •••	Rear A ••• ••• Front
RD/A	RS-232 Receive	RS-485A
TD/B	RS-232 Transmit	RS-485B
СОМ	Ground	Blank

7. 1/0

The basic type has one passive input and 4 relay open output

Basic type Pin's definitions:

Pins	Signal	Note
OUT1	Output 1	
OUT2	Output 2	Output properties:
OUT3	Output 3	AC: 30~250VAC/1A
OUT4	Output 4	DC: 5~30VDC/2A
OUT_COM	Output common port	
IN1	Input 1	High level: 10 \sim 24VDC
IN_COM	Input common port	Low level: $0{\sim}3VDC$

I/O interface drawing:





Output - 0M/00/01/02/03 Input - IM/I0/I1

Y320-IO has 4 passive input and 8 relay open output

Pins definitions:

引脚	信号	说明
OUT5	Output 5	
OUT6	Output 6	
OUT7	Output 7	
OUT8	Output 8	Output properties:
OUT9	Output 9	AC: 30~250VAC/1A
OUT10	Output 10	DC: 5~30VDC/2A
OUT11	Output 11	
OUT12	Output 12	
OUT_COM	Output common port	
IN2	Input 2	
IN3	Input 3	
IN3	Input 3	High level: $10 \sim 24$ VDC
IN4	Input 4	
IN_COM	Input common port	

8. Analog Quantity Output

 $Y320\ supply many types of analog signals which with proportional output according to the weight of the scale$

Pins	Signal	Note
VOUT	Voltage output	Output resistance 0 \sim 600 Ω , output can be:
GND	Voltage output	$0 \sim +5V; 0 \sim +10V; -5V \sim +5V; -10V \sim +10V;$
	Electric	
1001	current output	Output can be:
	Voltage output	4mA \sim 20mA; 0mA \sim 20mA; 0mA \sim 24mA
GND	GND	
SHLD	Shield	

	\sim	Vout
		GND
		Iout
		GND
		SHLD
\odot		

9. Parameter Set

9.1 Enter setting menu

On weighing mode, keep pressing

sing **ENTER**

key to enter parameter setting mode.

9.2 Quit Setting

On any mode, continuous press



4

key to return to previous step or quit the setting mode.

9.3 Main Set Menu



9.4 System Parameter Set



9.4.1 Scale Set

 CAPACITY INCREMENT CAL. UNIT CAL. ZERO 	Press SELECT key or TARE key to
 ◆ CAL. SPAN ◆ CAL. BOTH ◆ CHECK PARAM ◆ EXPAND 	key to enter the chosen menu, press

Max.capacity



Division



Calibration Unit



Zero Calibration



Weight Calibration



◆ CAL. SPAN LOAD WEIGHT	Put the weight on the scale	
 ◆ CAL. SPAN ₩EIGHT: 000.000 	Input the weight value the same as the calibration weight Press SELECT key to move the cursor. Press Key to change the digits. Press Key to save the change and start to calibrate. Press Key to cancel and return.	
◆ CAL. SPAN PROGRESS 60%	The indicator is sampling the A/D data of calibration point, it ends when it became 0% from 100%.	
◆CAL. SPAN TOO SMALL!	The weight value is too small. Trouble shooting: 1、 The weight is really too light. 2、 Wrong connection of the signal cable or excitation cable	
◆CAL. SPAN CAL SUCCESS!	Calibration done.	

Full Calibration

This calibration is jointed the zero calibration and weight (capacity) calibration, prease refer to above steps.







9.4.2 Operation Set

 ◆ TARE ALLOW ◆ PWR-UP ZERO ◆ KEYPAD ZERO ◆ AZM RANGE 	Press SELECT key or TARE key to choose the menu to be set, press
 MOTION ♦ FILTER ♦ BUZZER SOUND 	key to enter. Press ZERO key to return the previous step.

Tare Operation



Zero upon Power on

► PWR_IIP 7FRO	Choices: 0%, 2%, 20%
	Press SELECT or TARE key to change
2 %	Press ENTER key to save and return.
	Press ZERO key to cancel and return.

Zero by Keypad



Zero Tracking



Vibration checking







<u>Buzzer Set</u>



9.4.3 Batching Set



Batching mode:



Material quantity



Feeding door

	1: single door single speed
	2: double doors double speed
	If there is no I/O board, only M1 can be set
◆ DOORS	Press key to move cursor.
M1 M2 M3 M4	Press key to modify the chosen digits.
	Press ENTER key to save and return to
	Press ZERO key to cancel and return to
	previous step.





Press	ربه ENTER	key to save change and return.
Press	►04 ZERO	key to cancel and return.

Feeding action



Discharge mode





Empty scale range

Frequency Adjust



<u>Time Parameter</u>



Delay start time



Comparing time forbidden



Press key to save and return to previous step.
Press ZERO key to cancel and return to previous step.

Delay checking time



	Choice: $0.0 \sim 9.9$ seconds.
	scale, it will close the door after this time, to make sure full discharge.
◆UNLOAD TIME	Press SELECT key to move cursor.
1 0 9	Press key to modify the chosen
L.SU∖ S	Press key to save and return to
	previous step.
	Press ZERO key to cancel and return to previous step.

Tolerance checking frequency

◆TOL FREQ 1	Choice: $0 \sim 99$ Checking tolerance after the times of batching, if it was set of 0, it will not check.
	Press SELECT or TARE key to change Press key to save change and
	Press key to cancel and return.

Tolerance range set



First material tare

A EIDOT TADE	×: The first material doesn't need tareJ: The first material need tare
VITASI TAKE	
FIRST TARE? \times	Press ENTER key to save change and return.
	Press ZERO key to cancel and return.

Cycle times of batching



<u>Adjust range</u>



9.4.4 Communication protocol



			ADDRESS	◆ NODE
--	--	--	---------	--------

Output mode



Baud rate

	Choice: 300 bit/s; 600 bit/s;
	1200 bit/s; 2400 bit/s;
	4800 bit/s; 9600 bit/s;
● BAUDRATE	19200 bit/s; 38400 bit/s;
· · · · · · · · · · · · · · · · · · ·	57600 bit/s; 115200 bit/s;
19200	Press SELECT or TARE key to change
	Press ENTER key to save change and return.
	F04
	Press ZERO key to cancel and return.

Parity check



<u>Checksum</u>

	Choice: No transmitting Transmitting
◆ CHECKSUM	Press SELECT or TARE key to change
NO	Press ENTER key to save change and return.
	Press ZERO key to cancel and return.

Indicator address



9.4.5 Analog quantity output



Output type choose

◆FIELD MAP	Choice: $0 \sim +5V$; $0 \sim +10V$; -5V $\sim +5V$; -10V $\sim +10V$; 4mA ~ 20 mA; 0mA ~ 20 mA;
4 ~ 2 0mA	Press SELECT or TARE key to change Press key to save change and return.



Zero calibration (coarse-small-fine)

◆ZERO. COARSE
000000
◆ZERO. SMALL
000000
◆ZERO. FINE
00000

Full scale calibration (coarse-small-fine)





5.4.6 Diagnosis and maintenance

 ◆ RELOAD ◆ FREE CAL ◆ INPUT TEST ◆ OUTPUT TEST 	Press key or key to
 ◆BACKUP ◆RELEASE ◆OUT MAPPING 	choose the menu to be set, press ENTER key to enter. Press Press key to return the previous step.

<u>Reload</u>

◆RELOAD RELOAD? ×	Choose √ to reload the default parameters
◆RELOAD RELOAD	Reloading

◆FREE CAL FREE CAL? ×	Choose √ to enter
	Menus
 CAPACITY SENSITIVITY CAL. ZERO MANUAL MEND 	Press SELECT key or TARE key to choose the menu to be set, press key to enter. Press ZERO key to return the previous step.
	Input the full capacity of load cells
◆ CAPACITY	Press SELECT key to move cursor. Press key to modify the chosen
000100	digits. Press ENTER key to save and return to previous step.
	Press key to cancel and return to previous step.
	Input the sensitivity of load cells
◆ SENSITIVITY	Press SELECT or TARE key to change
2 mV/V	Press ENTER key to save change and return.
	Press ZERO key to cancel and return.
◆CAL.ZERO EMPTY SCALE?	Zero calibration



Input interface test

◆ INPUT TEST	
INPUT TEST? \times	Choose √ to enter test menu
◆INPUT TEST	
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$	Input test interface

Output interface test



◆OUTPUT TEST	
<u>00000000</u> 0000	Output test interface

Backup parameters

◆ BACKUP BACKUP? ×	Choose √ to backup parameters
◆ BACKUP PASSWORD: 1186	Input the password
◆ BACKUP PASSWORD ERROR!	Password wrong
◆ BACKUP BACKUP	Backup

Retrieve the backup parameters

◆RELEASE RELEASE? ×	Choose √ to retrieve the backup parameters
◆ RELEASE NOT BACKUP!!	Indicates that there is no backup parameters
◆ RELEASE RELEASE	Retrieving

Alternate output mapping

◆OUT MAPPING TOL	Choices: Tolerance output, fast feeding output, fine feeding output, discharging output. If the original output interface broken or with problem, you can mapping that interface to this alternate one by changing the cables. Press SELECT or TARE key to change Press key to save change and
	return.
	Press ZERO key to cancel and return.

9.5 Recipes Parameters set

	Press SELECT key or Key to
Basic + 4 materials type	choose the menu to be set, press
	key to enter.
	Press ZERO key to return the previous



<u>M1 recipe set</u>

 M1 TARGET M1 FINE M1 PREACT 	Press SELECT key or TARE key to choose the menu to be set, press key to enter. Press ZERO key to return the previous step.
	Target weight:
	tank/container.etc
◆M1 TARGET	Press select key to move cursor.
	Press TARE key to modify the chosen
010.000	digits. Press ENTER key to save and return to
	previous step.
	Press ZERO key to cancel and return to previous step.
	Fine weight:
	The relative weight between TARGET and
	FAST (when it finish the fast filling and
	change to fine filling), it's the relative value
	but not actual value.
◆M1 FINE	Press select key to move cursor.
	Press TARE key to modify the chosen
<u>U</u> U2.000	digits. Press key to save and return to
	Press ZERO key to cancel and return to previous step.



M2、M3、M4 recipes the same as M1

<u>Recipe numbers set</u>



Upper and lower weight limitations

	It needed to be set when it using for losing
<pre>◆LOWER LIMIT </pre> OO2.000	weight filling Lower limitation: the minimum remaining after the end of discharging. Upper limitation: the approximated maximum weight it can reach.
◆UPPER LIMIT	During feeding, if the weight <(target + lower limitation), the indicator will open the supplement feeding valve until the weight reach to upper limitation and then start to discharge.
	Note: If the target weight < (Upper limitation - Lower limitation), every start will end after once time discharge.

-
If the target weight > (Upper limitation -
Lower limitation), it will discharge more
times until it reach to the target value.
Press SELECT key to move cursor.
Press TARE key to modify the chosen
digits.
Press ENTER key to save and return to
previous step.
Press ZERO key to cancel and return to
previous step.

<u>Setpoint 1</u>



Setpoint 2 and setpoint 3 the same as above set.

Preaction 1 set



Preaction 2 and preaction 3 the same set as above

9.6 Printing table format



9.7 System set



10. Appendix: Communication Protocol

10.1 Continuous transmitting format A

Format A

						[Data	forma	at (1	8 byt	es)						
STX	A	В	С	х	х	х	Х	Х	Х	Х	Х	х	х	Х	Х	CR	CKS
I]	V			V	VI					

I、 <STX>ASCII start sign (02H)。

 \amalg_{\sim} status $A_{\sim}~B_{\sim}~C,~$ refer to below table

 ${
m III}$. Weight value, gross weight or net weight, 6 ASCII digits without sign and decimal point.

- IV. Tare value, 6 ASCII digits without sign and decimal point.
- V、 <CR>ASCII Enter sign (ODH)。
- VI、 <**CKS**> checksum

BIT	Status A	Status B	Status C
Bit0	Decimal point position:	0=Current value is gross 1=Current value is net	000 : Stop 001 : Material 1 feed 010 : Material 2 feed
Bit1	001:XXXXX0 010:XXXXXX 011:XXXXX	0=Display value is positive 1=Display value is negative	010 : Material 2 feed 011 : Material 3 feed 100 : Material 4 feed
Bit2	100:XXXX.XX 101:XXX.XXX	0=Within display range 1=Out of display range	101 : Discharging 110 : Batching Suspense 111 : Batching run
Bit3	Fast feed output 0=Off 1=On	0=Current weighing stable 1=Current weighing unstable	Always 0
Bit4	Fine feed output 0=Off 1=On	Always 1	0 : stand display 1 : ×10 display
Bit5	Always 1	Always 1	
Bit6	Always 0	Always 0	
Bit7	Always 0	Always 0	

10.2 Command transmitting format A

	<u> </u>	
No.	Command sign	Note
1	"C" or "c"	Clear tare
2	"P" or "p"	Print gross tare net
3	"T" or "t"	Tare
4	"Z" or "z"	Zero

10.3 Continuous transmit format B



10.4 Command output format B

No.	Command letter	Indicator response
1	READ+ENTER NEWLINE	Refer to <indicator and="" reading="" status="" weight=""></indicator>
2	TARE+ ENTER NEWLINE	Refer to <tare and="" reading="" status="" weight=""></tare>
3	TARE ON+ ENTER NEWLINE	Tare operation Works: return YES+ ENTER NEWLINE No work: return NO? + ENTER NEWLINE
4	TARE OFF+ ENTER NEWLINE	Clear tare Works: return YES+ ENTER NEWLINE No work: return NO? + ENTER NEWLINE
5	ZERO ON+ ENTER NEWLINE	Zero operation Works: return YES+ ENTER NEWLINE No work: return NO? + ENTER NEWLINE
6	CAL XXXXXX+ ENTER NEWLINE	XXXXXX is loading weight value, W, without decimal point If W=0, zero calibration. If W≠0, loading weight calibration. Indicator response: Zero calibration done: ZERO YES+ ENTER NEWLINE Zero calibration vibrate: ZERO E1+ ENTER NEWLINE Loading weight calibration done SPAN YES+ ENTER NEWLINE Loading weight calibration vibrate: SPAN E1+ ENTER NEWLINE Input data is too small: SPAN E2+ ENTER NEWLINE Input data is too big: SPAN E3+ ENTER NEWLINE Loading weight is too big: SPAN E4+ ENTER NEWLINE

Indicator weight reading and status, the indicator response format:



Tare weight reading and status, the indicator response:



10.5 MODBUS output format

MODBUS is the master-slave type network communication protocol, this indicator acts as the subordinate in the network for called by the host system, the format is RTU and support 03 and 06 functions. The parameter needs to be set as F4.1=5 and the address of Modbus to set in F4.5, the mapping address definitions as the below table:

Address	Digits	Note (read only)				
40001		Current gross weight value				
40002		Current display weight value				
	.0	1=material 1 in fast feeding				
	.1	1=material 1 in fine feeding				
	.2	1=scale is empty				
	.3	1=reach to setpoint 1 (setpoint type)				
	.4	1=material 2 in fast feeding				
	.5	1=material 2 in fine feeding				
40002	.6	1=reach to setpoint 2 (setpoint type)				
40003	.7	1=reach to setpoint 3 (setpoint type)				
	.8	1=material 3 in fast feeding				
	.9	1=material 3 in fine feeding				
	.10	1=supplement feeding (single material losing weight mode)				
	.11	1=Indicator above tolerance or lower than tolerance				
	.12	1=material 4 in fast feeding				
	.13	1=material 4 in fine feeding				
	.0					
	.1	$01 \sim 11$, current recipe numbers $(1 \sim 3)$				
	.2	or the current recipe numbers (1 3)				
	.3					
40004	.4	1=batching run				
40004	.5	1=batching suspense				
	.6	1=discharging				
	.7	1=feeding finish, waiting for discharging				
	.8 .9	0000=0.001; 0011=0.01; 0110=0.1; 1001=1;				

.10	0001=0.002; 0100=0.02; 0111=0.2; 1010=2;
	0010=0.005; 0101=0.05; 1000=0.5; 1011=5;
.11	1100=10: 1101=20: 1110=50:
	current division.
.12	1=batching tolerance
.13	1=scale vibrate
.14	1=manual feeding mode
.15	1=manual discharging mode
	$1 \sim 4$ material batching mode: actual batched weight of current material 1.
40005	Single material losing weight mode: the current batched value of this filling.
	(the batching value kept till start of next cycle).
	$1 \sim 4$ material batching mode: actual batched weight of current material 2.
40004	Single material losing weight mode: the current accumulated value of this
40006	filling.
	(the batching value kept till start of next cycle).
40007	actual batched weight of current material 3. (the batching value kept till start
40007	of next cycle).
40008	actual batched weight of current material 4. (the batching value kept till start
40008	of next cycle).
Address	Mapping (read and write)
40009	Tare value
40010	Target value of material 1
40011	Target value of material 2
40012	Target value of material 3
40013	Target value of material 4
40014	Fast feeding value of material 1
40015	Fast feeding value of material 2
40016	Fast feeding value of material 3
40017	Fast feeding value of material 4
40018	Preaction quantity of material 1
40019	Preaction quantity of material 2
40020	Preaction quantity of material 3
40021	Preaction quantity of material 4
40022	Range of empty scale
40023	Preaction adjust frequency
40024	Start delay time
40025	Discharge delay time
40026	Forbid comparing time
40027	Delay check time of material 1
40028	Delay check time of material 2
40029	Delay check time of material 3
40030	Delay check time of material 4
40031	Lower tank weight
40032	Upper tank weight
40033	Weight value of setpoint 1
40034	Weight value of setpoint 2
40035	Weight value of setpoint 3
40030	Preaction quantity of setpoint 1
40037	Preaction quantity of setpoint 2
40030	Preaction quantity or setpoint 3
40039	Qualitity used of material 1 (higher digits)
40040	Qualitity used of material 2 (lower digits)
40041	Qualitity used of material 2 (Inglier digits)
40042	Qualitity used of material 2 (lower digits)
40043	Qualitity used of material 2 (lawor digits)
40044	Qualitity used of material 4 (bigher digits)
40040	Qualitity used of material 4 (inglief digits)
40040	

	0	1=Zero calibration done						
	1	1=Loading weight calibration done						
400.47	2	1=Writing value less than 1% during loading weight calibration						
40047	3	1=Writing value more than full scale during loading weight calibration						
	4	1=Loading weight is not enough during loading weight calibration						
	5	1=running, calibration not allowed						
4004	18	Floating number of current weight						
4004	19							
Address		Mapping (Write only)						
	.0							
	.1	$0001 \sim 0100$, appoint the material number to be operated						
	.2							
	.3							
		Start manual feeding, material bits 0-3 given:						
		(Eg: If 0001: material 1 batching,						
	.4	If 0010: material 2 batching,						
		If 0011: material 3 batching,						
		If 0100: material 4 batching)						
40101	.5	/						
40101	.6							
	.7	/						
	.8	Start auto feeding						
	.9	Suspend batching or discharging						
	.10	Stop emergency						
	.11	Start discharge (after feeding end and discharging type is manual)						
	.12	Tare (not batching, not vibrate and tare allowed)						
	.13	Clear tare (not batching, not vibrate and tare allowed)						
	.14	Zero (not batching, not vibrate)						
	.15	Continue batching or discharging						
	.0							
	.1	$0001 \sim 0011$. Choose working recipe number						
	.2							
40102	.3							
40102	.4	10: Chose manual batching during all cycles.						
	.5	11: Chose auto batching during all cycles.						
	.6	10: Chose manual discharging during all cycles.						
	.7	11: Chose auto discharging during all cycles.						
		Scale calibration:						
4010)3	0: Zero calibration						
		XXXXX: loading weight calibration (XXXXX is the value of the loading weight)						

10.6 Multi materials jointed work with relay connected

The below chart is for connecting of 4 materials batching, the input and output can be connected as common source or common grounded, for single material, connect the three relay to the connecting terminals of fast feeding, fine feeding and discharging.













HIVEIGH An ISO9001 registered company @No.335 Haishen, Xingxin Road, Huinan Town, Pudong District, Shanghai 201301, China Weighing system & solution Www.hiweigh.com All rights reserved, specifications subject to change without notice